



S&W Race Cars and Components, Inc.

11 Mennonite Church Road
Spring City, PA 19475

TECH & INFORMATION: 610-948-7303


ORDERS: 1-800-523-3353

OFFICE FAX: 610-948-7342

E-Z INFO FAX 610-792-1234

CAUTION!!! - The most important requirement for a successful installation of this, or any, S&W chassis component is that you take your time and use good common sense. Check & recheck all measurements before cutting or welding. If you have any questions, before or during the installation - STOP - and call our tech line at 610-948-7303 and we will gladly explain in more detail any step in the installation.

Supplemental Instructions for Installing 40-613 Torsional Anti Roll Bar on 1993 and Newer Camaros & Firebirds



It has come to our attention that some 1993 - 2002 Camaros & Firebirds are equipped with an additional floor pan brace located near the top on the forward side of the rear housing area. Installation of part # 40-613 Torsional Anti Roll Bar on 1993 - 2002 Camaros & Firebirds equipped with this brace will require you to notch the brace for mounting bracket clearance. We suggest you bolt the right & left floor connector to the torsion tube weldment and hold the assembly up in it's

location. Then mark the brace for the area that requires trimming for clearance around the mounting brackets.

See the photos for examples

